

Problem Set 10

ENGR 12, Spring 2026.

Due Date	Thu, Apr 9
Turn in link	Gradescope
URL	emadmasroor.github.io/E12-S26/Homework/HW10

Points Distribution

Please note that each of the following grade items is a **single rubric item**. Each rubric item is scored on a four-level scale of 3-2-1-0. You may wish to take this into account when deciding how to allocate your efforts to each problem.

Problem	% Weightage
Problem 1	25
Problem 2	25
Problem 3	25
Problem 4	25

1 Making Bode Plots

1.1 Programmatically

Draw the Bode plots (magnitude only) for the following systems on the same set of axes:

1. $T(s) = \frac{1}{10s + 1}$

2. $T(s) = \frac{1}{s + 5}$

3. $T(s) = \frac{1}{0.1s + 1} + \frac{1}{100s + 1}$

i Note


You may wish to use the code provided on the [resources page](#). You do not need to submit your code.

1.2 Sketching

Sketch the Bode plots (magnitude only) for the following systems on the given set of axes. Label the corner frequency (in radians per second) for each case using a vertical line, and give its numerical value.

1. $T(s) = \frac{1}{s + 100}$

2. $T(s) = \frac{1}{5s + 1}$

Bode Plot for system $T(s)$ 

2 Plotting $T(i\omega)$ on the complex plane for multiple transfer functions

We have learned that the complex number $T(i\omega)$, where $T(s)$ is the transfer function of a system, tells us about the amplitude ratio and phase shift of the steady-state response of that system relative to a sinusoidal input provided to it.

For the following transfer functions, plot $T(i\omega)$ on the complex plane (i.e., put $\text{Re}T(i\omega)$ on the horizontal axis and $\text{Im}T(i\omega)$ on the vertical axis). Use $\omega = 2$. You must put all of your points (six in total) on the same pair of axes, and you must label them with the transfer function expressions, either using ‘callouts’ or using a legend.

i Note

You can replace the plot with a very neatly-drawn and (within reason) quantitatively accurate sketch, if you prefer.

i Note

You may use a computer to help you with these calculations, but on a test you will be expected to this “by hand” with only a handheld calculator, if that. So it’s best to work this out manually.

1. $T(s) = \frac{1}{s + 5}$
2. $T(s) = \frac{1}{s - 5}$
3. $T(s) = \frac{1}{0.2s + 1}$
4. $T(s) = \frac{1}{2s - 1}$
5. $T(s) = \frac{1}{s + 3i}$
6. $T(s) = \frac{1}{s - 3i}$

3 Plotting $T(i\omega)$ on the complex plane for multiple values of ω .

Consider the transfer function

$$T(s) = \frac{1}{5s + 1}, \quad (1)$$

subjected to sinusoidal inputs of unit magnitude and angular frequency equal to $\{0.01, 0.1, 0.2, 2, 10\}$.

3.1 On the complex plane

Plot $T(i\omega)$ for each of the above values of ω on the complex plane.

3.2 Plotted against ω


Plot $|T(i\omega)|$ and $\angle T(i\omega)$ against ω for the five values of ω given above. There will be a total of two plots, and each plot will have five data points only. You may or may not choose to connect your five points with a curve or lines.

i Note

The axes on your plots should not be logarithmic.

3.3 Bode Plot

Draw the Bode plot for the system given by Equation 1. You may choose to use plotting software, or sketch a quantitatively accurate graph on the following set of axes. In either case, use the given axis limits and grid markings.

Bode Plot for system $T(s)$ 

4 Amplitude Ratio and Phase Shift

A certain linear system has input $f(t)$ as shown in the graph below, and the corresponding steady state output $x_{ss}(t)$, also shown on the same axes.




Figure 1

i Note

The transients, if any, are *not* shown in this graph.

4.1 Order of the system

Determine, if possible, the order of this system.

- It is definitely a first order system
- It is definitely a second order system
- It is a higher-order system (3rd or greater)
- It is not possible to tell from the given information

4.2 Magnitude and argument of $T(i\omega)$

i Note

The magnitude of a complex number z is denoted by the symbol $|z|$ or sometimes $\text{abs}(z)$. The argument of a complex number z is denoted by the symbol $\angle z$ or $\arg z$.

If the transfer function for this system is given by $T(s)$, determine the magnitude and argument of $T(i\omega)$ for $\omega = 1$. Present this information visually in the form of a complex plot, where the real part

of $T(i\omega)$ is shown on the horizontal axis and the imaginary part of $T(i\omega)$ is shown on the vertical axis. You must also give the numerical values of $|T(i\omega)|$ and $\angle T(i\omega)$.

i Note

This question asks you to visually interpret Figure 1. For the vertical axis, read the graph to the closest half-interval, and for the horizontal axis, read the graph in increments of 15° . Do not give the answer in angles of greater than $+180^\circ$ or less than -180° .

4.3 Identifying the Transfer Function

Which of the following could be the transfer function for this system?

💡 Hint

Calculate $|T(i\omega)|$ and $\angle T(i\omega)$ for each transfer function and compare with the values you expect.

- $\frac{1}{s+i}$
- $\frac{1}{s+1}$
- $\frac{1}{s+2}$

4.4 Lag vs. Lead

The situation in Figure 1 can be described in the following words: the output $x(t)$ **lags** the input $f(t)$ by [some number of degrees or radians]. This refers to the fact that a peak in $f(t)$ occurs first, and after some time (known as the lag duration), a peak in $x(t)$ occurs. The opposite of ‘to lag’ is ‘to **lead**’.

Sketch, on a copy of the graph shown, an output signal $x_2(t)$ that has an amplitude ratio 0.5 and that *leads* the input signal $f(t)$ by

1. 90 degrees
2. 45 degrees